





NOTE: VERIFY P4/P5/P6 WIRING BEFORE
CONNECTING LIGHTING SYSTEM. VERIFY
MON-G960 FUSE F2 IS INSTALLED.


DLS1-008R

TOP MASTER



DLS1-008R

MID 1 SLAVE



DLS1-008R

MID 2 SLAVE

