


MON-9700


ILS-3600-0IR/2600-0IR



NOTE: VERIFY P12/P13/P14 WIRING BEFORE CONNECTING LIGHTING SYSTEM.
VERIFY MON-9700 FUSE F2 IS INSTALLED.

MON-9700


ILS-3400/2400



NOTE: VERIFY P12/P13/P14 WIRING BEFORE CONNECTING LIGHTING SYSTEM.
VERIFY MON-9700 FUSE F2 IS INSTALLED.

MON-9700

PC-324/312/311/310




NOTE: VERIFY P12/P13/P14 WIRING BEFORE CONNECTING LIGHTING SYSTEM.
VERIFY MON-9700 FUSE F2 IS INSTALLED.

* NOT PRESENT
ON PC-310

MON-9700

FTS-370D



NOTE: VERIFY P12/P13/P14 WIRING BEFORE CONNECTING LIGHTING SYSTEM.
VERIFY MON-9700 FUSE F2 IS INSTALLED.