


FTC-161

MON-930



NOTE: VERIFY P2/P3 WIRING BEFORE
CONNECTING LIGHTING SYSTEM.
REMOVE MON-930 FUSE F1.

