



MON-9x0




JUMPER




NOTE: VERIFY P2/P3 WIRING BEFORE  
CONNECTING LIGHTING SYSTEM.  
INSTALL MON-9x0 FUSE F1.


## ILS-3400 Top (Master)




VOLTAGE  
PHOTOCELL



PEC POWER



## ILS-3400 Mid1



## ILS-3400 Mid2

